

2852 Alton Ave., Irvine, CA 92606 (949) 261-1022 FAX (949) 261-1228
1014 E. Cooley Dr., Sulte A, Colton, CA 92324 (909) 370-4867 FAX (909) 370-1046
7277 Hayvenhurst, Sulte B-12, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1843
9484 Chesapeake Dr., Sulte 805, San Diego, CA 92123 (858) 505-8596 FAX (858) 505-8689
9830 South 51st St., Sulte B-120, Phoenix, AZ 85044 (480) 785-0043 FAX (480) 785-0851
2520 E. Sunset Rd. #3, Las Vegas, NV 89120 (702) 798-3620 FAX (702) 798-3621

STL Los Angeles 1721 S Grand Avenue Santa Ana, CA 92706 Attention: Diane Suzuki

Client Project ID E2F010157

Report Number: PLF0033

Sampled: 05/31/02 Received: 06/04/02 Issued: 6/20/02

GASIONA ERAGUATE

LABORATORY NUMBER PLF0033-01RE1

PLF0033-01RE1 PLF0033-02RE1 PLF0033-03 SAMPLE DESCRIPTION

> SP-37 SP-36 SP-38

SAMPLE MATRIX

> Soil Soil Soil

SAMPLE RECEIPT:

Samples were received intact, on ice, at 10°C, and with chain of custody documentation.

HOLDING TIMES:

Holding times were met.

PRESERVATION:

Samples requiring preservation were verified prior to sample analysis.

OBSERVATIONS:

No significant observations were made.

SUBCONTRACTED:

No analyses were subcontracted.

QA/QC CRITERIA:

All analyses met method criteria.

EXPLANATION OF DATA

QUALIFIERS:

No further explanation of data qualifiers needed.

Del Mar Analytical, Phoenix (ELAP I-2446/NELAP# 01109CA)

Nicole Beck For Debbie Fuller

Project Manager

The results pertain only to the samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

000082

PLF0033 Page 1 of 12